ECG Contest

ECG, December 2018

ECG de diciembre de 2018

Ana Fernández-Vega,^{a,*} Daniel Enríquez-Vázquez,^a and Julián Palacios-Rubio^b

^a Instituto Cardiovascular, Hospital Clínico San Carlos, Madrid, Spain

^b Unidad de Arritmias, Instituto Cardiovascular, Hospital Clínico San Carlos, Madrid, Spain

A 75-year-old man was referred to the emergency room with symptoms of dizziness and poor pacemaker function after the ECG shown in the Figure was recorded. He had a history of permanent atrial fibrillation (AF) and percutaneous revascularization of ischemic heart disease, with moderate systolic left ventricular dysfunction. For 1 year, he had been a carrier of a Meditronic cardiac resynchronization therapy pacemaker (CRT-P) in VVIR mode for AF with complete atrioventricular block (lower rate limit, 70 bpm; maximum tracking rate, 130 bpm; bipolar sensing and pacing; atrial port plugged for permanent AF).



Figure.

In view of the ECG (Figure), is this pacemaker malfunctioning?

- 1. The CRT-P device is working appropriately.
- 2. This is a sensing issue. The intracardiac electrogram of the ventricular extrasystole probably has a lower voltage than the programmed sensitivity.
- 3. The CRT-P device does not have sensing defects, although resynchronization should be optimized.
- 4. The CRT-P device is operating after activation of the elective replacement indicator, as it only works with right-sided pacing at the lower rate limit.

Suggest a diagnosis to this ECG Contest at http://www.revespcardiol.org/en/electroreto/71/12. The answer will be published in the next issue (January 2019). #RetoECG.

* Corresponding author:

E-mail address: afvega@salud.madrid.org (A. Fernández-Vega).

https://doi.org/10.1016/j.rec.2018.05.006



^{1885-5857/© 2018} Sociedad Española de Cardiología. Published by Elsevier España, S.L.U. All rights reserved.